








Instruction Manual | Bedienungsanleitung | Manual de instrucciones | Manuale d'istruzioni | Manuel d'instructions  
Handleiding | Návod k použití




5 x 1.5-2.5mm<sup>2</sup>  
H05RN-F  
ø 13.4mm



www.megaman.cc/user-guide




Output current setting



PIN1	PIN2	PIN3	I <sub>out</sub> (mA) AC input	I <sub>out</sub> (mA) DC input
ON	ON	ON	950	171
OFF	ON	ON	850	153
ON	OFF	ON	800	144
ON	ON	OFF	750	135
OFF	OFF	ON	700	126
OFF	ON	OFF	650	117
ON	OFF	OFF	600	108
OFF	OFF	OFF	500	90



◀ Default Preset: 850mA

Instruction Manual | Bedienungsanleitung | Manual de instrucciones | Manuale d'istruzioni | Manuel d'instructions |  
Handleiding | Návod k použití



**WARNING:**

- THIS CLASSIFICATION IS NOT SUITABLE FOR HIGH-RISK TASK AREA LIGHTING;
- AUTOMATIC RESRTTING TYPE.

	<b>I</b>	<b>U</b>	<b>λ</b>	<b>I</b>	<b>U</b>	<b>Ta</b>	<b>Tc</b>
DRIVER	Input			Output			
LD232037/da/ mc-C0950	Max. 190mA	220-240V≈0/ 50/60Hz	>0.9	950mA 850mA 800mA 750mA 700mA 650mA 600mA 500mA	30-45VDC	-30°C...+40°C	+85°C